

## **Tarp Canopy Over The Paper Machine Wet End To Prevent Condensation Drippage Onto The Machine Of No. 6 Paper Machine In Naheola Alabama**

This paper machine building had roof condensation and corrosion problems for many years which is why the tarp in this picture was hung over the forming section of the machine. The building and paper machine was installed in 1966 and in 1987 the roof was replaced. Then in 1990 the roof was replaced again along with four of the box girders over the machine that had too much deflection. The cost of the 1990 replacement was \$1,300,000 for a 20,328 ft<sup>2</sup> roof.

